

## Plaza Ferdinand VII

### Cost Break down for repair.



Grand total \$75,000

The Fountain lights will be a separate project after the completing of the repairs. \$15,000  
(4) new lights will be added into the fountain.