FY 2018 CRA Asset Condition Inventory Maintenance Needs Cost Estimates

	Total #	Condition Description	Good	Fair	Poor	•	ure Wash/Paint)	•	cement	Sub-Totals	Area Total	Ì
Plaza de Luna			No Maint	Maint	Replace	Unit Cost	Total Cost	Unit Cost	Total Cost			
Benches	23	all in fair condition - need painting and pressure washing	0	23	0	100	\$2,300	1000	\$0	\$2,300		
Garbage Cans	10	7 have to be replaced, 3 are in fair condition	0	3	7	100	\$300	1000	\$7,000	\$9,600		
Bollards	8	2 need to be replaced other need to be painted	0	6	2	100	\$600	1100	\$2,200	\$12,400		
Light Poles	15	Needs painting/pressure washing	0	15	0	100	\$1,500	0	\$0	\$13,900		
Railing	1	Poor	0	1	0	100,000	\$100,000	0	\$0	\$113,900		
Paving	1	NA	0	0	1	0	\$0	75,000	\$75,000	\$188,900		
Kid Gates	6	NA NA	0	0	6	0	\$0	500	\$3,000	\$191,900		
Water Fountains	1	Poor	0	0	1	0	\$0	1,500	\$1,500	\$193,400		
Parking Spaces	27	Good	0	0	0	0	\$0	0	\$0	\$193,400	\$193,400	
Faiking Spaces	21	d000	0	- 0	0	<u> </u>	3 0	0	3 0	\$193,400	\$200,000	 Estimate
S Palafox Streetscape - From Garde	en St to Plaza de Lu	na (Excluding Promenade)									3200,000	Latinate
Benches	6	All fair condition - paint/pressure wash	0	6	0	100	\$600	1000	\$0	\$600		
Garbage Cans	25	All need to be replaced.	0	0	25	100	\$0	1000	\$25,000	\$25,600		
Bollards	34	All need to be replaced.	0	34	0	100	\$3,400	1100	\$0	\$29,000		
Light Poles	88	Needs painting/pressure washing	0	88	0	100	\$8,800	0	\$0	\$37,800	\$37,800	
Light Foles	- 00	Needs painting/pressure washing		00		100	70,000		70	737,000	\$40,000	 Estimate
N Palafox Streetscape and MLK Pla	za - From Wright 9	it to Garden St									\$40,000	Lotimate
Benches	22+	Figure represents MLK Plaza only. All good, replaced a few years	22	0	0	100	\$0	1000	\$0	\$0		
Garbage Cans	14+	Figure represents MLK Plaza only. Fair condition	0	14	0	100	\$1,400	1000	\$0	\$1,400		
Light Poles	77	Needs painting/pressure washing	0	77	0	100	\$7,700	0	\$0	\$9,100	\$9,100	
0 1 1 1		b 0, p 0	-				, ,			1-7	\$10,000	Estimate
Palafox Pier Promenade												
Light Poles	8	Needs painting/pressure washing	0	8	0	100	\$800	0	\$0	\$800		
Fountain	1	Good	0	1	0	0	\$0	0	\$0	\$800	\$800	
											\$1,000	Estimate
Garden St Streetscape and Median												
Benches	2	All fair condition - paint/pressure wash	0	2	0	100	\$200	1000	\$0	\$200		
Garbage Cans	5	All fair condition - paint/pressure wash	0	5	0	100	\$500	1000	\$0	\$700		
Light Poles	48+	Decorative lights need painting/pressure washing.	0	48	0	100	\$4,800	0	\$0	\$5,500	\$5,500	_
											\$6,000	Estimate
Jefferson St Streetscape - From Ga			_	_	_							
Benches	8	All fair condition - paint/pressure wash	0	8	0	100	\$800	1000	\$0	\$800		
Garbage Cans	14	All fair condition - paint/pressure wash	0	14	0	100	\$1,400	1000	\$0	\$2,200	4	
Light Poles	52	Needs paint/pressure washing	0	52	0	100	\$5,200	0	\$0	\$7,400	\$7,400	_
Delay and /Delgillana											\$8,000	Estimate
Belmont/DeVilliers	4	All fair and disian point/processes	0	4	0	100	\$400	1000	\$0	\$400		
Benches Carbago Cans	-	All fair condition - paint/pressure wash	0	4	0 0	100	\$400 \$400	1000	\$0 \$0			
Garbage Cans	4	All fair condition - paint/pressure wash	-	-	4					\$800		
Bollards	4	Not functioning	0	0 30	0	100 100	\$0 \$3,000	1100 0	\$4,400	\$5,200		
Light Poles	19	Fair - All need painting/pressure washing.	0 TBD	30 1	0	100 500	\$3,000 \$500	0	\$0 \$0	\$8,200		
Sidewalks	TBD TBD	Fair - Needs pressure washing.	TBD	0	0	0	\$500 \$0	0	\$0 \$0	\$8,700	\$8,700	
Pavers	IBD	Good	IRD	U	U	U	\$0	U	\$0	\$8,700	\$8,700	
Belmont/DeVilliers - Coyle Street	Parking Lot										\$9,500	Estimate
Sign Post	Parking Lot 1	Fair - Needs painting/pressure washing	0	1	0	100	\$100	0	\$0	\$100		
Streetlight	1	Fair- Needs painting/pressure washing/new globes	0	1	0	100	\$100	0	\$0 \$0	\$200		
Parking Spaces	TBD	Fair - May need restriping	0	0	0	0	\$100	0	\$0	\$200	\$200	

1

FY 2018 CRA Asset Condition Inventory Maintenance Needs Cost Estimates

	Total #	Condition Description	Good	Fair	Poor	Maint (Pressure Wash/Paint)		Replacement		Sub-Totals	Area Total	
		•	No Maint	Maint	Replace	Unit Cost	Total Cost	Unit Cost	Total Cost			
Seville Square												
Benches	12	All fair condition - paint/pressure wash	0	12	0	100	\$1,200	1000	\$0	\$1,200		
Garbage Cans	6	fair condition	0	6	0	100	\$600	1000	\$0	\$1,800		
Light Poles	18	fair condition	0	18	0	100	\$1,800	0	\$0	\$3,600	\$3,600	_
											\$4,000	Estimate
Henry Wyer Park												
Benches	7	All fair condition - paint/pressure wash	0	7	0	100	\$700	1000	\$0	\$700		
Garbage Cans	4	fair condition	0	4	0	100	\$400	1000	\$0	\$1,100		
<u>Bollards</u>	<u>7</u>	fair condition	<u>0</u>	<u>7</u>	<u>0</u>	<u>100</u>	<u>\$700</u>	<u>1100</u>	<u>\$0</u>	\$1,800		
Light Poles	6	fair condition	0	6	0	100	\$600	0	\$0	\$2,400	\$2,400	_

\$3,000 Estimate

\$282,000 Estimate

\$38,000 Contingency

\$320,000